

(3) A company or business if the employee or the employee's spouse or dependent child owns or controls more than 10 percent of its equity; or

(4) A partnership if the employee or the employee's spouse or dependent child is a general partner.

(b) *Exceptions*—(1) *Consumer credit on nonpreferential terms.* Disqualification of a supervisory employee is not required by paragraph (a) of this section for the following types of indebtedness if payment on the indebtedness is current and the indebtedness is on terms and conditions offered to the public:

- (i) Credit extended through the use of a credit card;
- (ii) Credit extended through use of an overdraft protection line;
- (iii) Amortizing consumer credit (e.g., home mortgage loans, automobile loans); and
- (iv) Credit extended under home equity lines of credit.

(2) *Indebtedness of a spouse or dependent child.* Disqualification is not required with respect to any indebtedness of the employee's spouse or dependent child, or a company, business or partnership in which the spouse or dependent child has an interest described in paragraphs (a)(3) and (a)(4) of this section, if:

(i) The indebtedness represents the sole financial interest or responsibility of the spouse, child, company, business or partnership and is not derived from the employee's income, assets or activities; and

(ii) The employee has no knowledge of the identity of the lender.

(c) *Waivers.* The Board's Designated Agency Ethics Official, after consulting with the relevant division director, may grant a written waiver from the disqualification requirement in paragraph (a) of this section using the authorization process set forth in the Office of Government Ethics' Standards of Ethical Conduct at 5 CFR 2635.502(d).

**§ 6801.108 Restrictions resulting from employment of family members.**

(a) *Reporting certain employment relationships.* A supervisory employee who has knowledge that his or her spouse, child, parent or sibling is employed by a depository institution or its holding company shall report such employment to his or her supervisor and the Ethics Office within thirty days of the commencement of the supervisory employee's employment at the Board or promptly upon learning of the employment relationship.

(b) *Disqualification.* A supervisory employee may not participate in any

particular matter to which a depository institution or its affiliate is a party if the depository institution or affiliate employs his or her spouse, child, parent or sibling unless the supervising officer, with the concurrence of the Board's Designated Agency Ethics Official, has authorized the employee to participate in the matter using the authorization process set forth in the Office of Government Ethics' Standards of Ethical Conduct at 5 CFR 2635.502(d).

**§ 6801.109 Prior approval for compensated outside employment.**

(a) *Approval requirement.* An employee shall obtain prior written approval from his or her division director (or the division director's designee) and the concurrence of the Board's Designated Agency Ethics Official before engaging in compensated outside employment.

(b) *Standard for approval.* Approval will be granted unless a determination is made that the prospective outside employment is expected to involve conduct prohibited by statute or Federal regulation, including 5 CFR part 2635 and this part.

(c) *Definition of employment.* For purposes of this section, the term compensated outside employment means any form of compensated non-Federal employment or business relationship involving the provision of personal services by the employee. It includes, but is not limited to, personal services as an officer, director, employee, agent, attorney, consultant, contractor, general partner, trustee, teacher or speaker.

**TITLE 12—BANKS AND BANKING**

**CHAPTER II—FEDERAL RESERVE SYSTEM**

2. 12 CFR part 264 is revised to read as follows:

**PART 264—EMPLOYEE RESPONSIBILITIES AND CONDUCT**

**§ 264.101 Cross-reference to employees' ethical conduct standards and financial disclosure regulations.**

Employees of the Board of Governors of the Federal Reserve System (Board) are subject to the executive branch-wide standards of ethical conduct at 5 CFR part 2635 and the Board's regulation at 5 CFR part 6801, which supplements the executive branch-wide standards, and the executive branch-wide financial disclosure regulation at 5 CFR part 2634.

Authority: 5 U.S.C. 7301; 12 U.S.C. 244.

[FR Doc. 95-30581 Filed 12-18-95; 8:45 am]

BILLING CODE 6210-01-P

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 1**

[Docket No. 25767; Notice No. 95-16]

RIN 2120-AF92

**Definitions of Special Use Airspace; Correction**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Correction to the notice of proposed rulemaking.

**SUMMARY:** This document contains a correction to the notice of proposed rulemaking (NPRM), 60 FR 58494, published on November 27, 1995. The correction to the address in the preamble reads as follows: Comments may also be sent electronically to the following Internet address: [nprmcmts@mail.hq.faa.gov](mailto:nprmcmts@mail.hq.faa.gov).

**ADDRESSES:** Comments on this NPRM should be mailed, in triplicate, to: Federal Aviation Administration, Office of the Chief Counsel, Attention: Rules Docket (AGC-200), Docket No. 25767, 800 Independence Avenue, SW., Washington, DC 20591. Comments may also be sent electronically to the following Internet address: [nprmcmts@mail.hq.faa.gov](mailto:nprmcmts@mail.hq.faa.gov). Comments delivered must be marked Docket No. 25767. Comments may be examined in Room 915G weekdays between 8:30 a.m. and 5 p.m., except on Federal holidays.

Issued in Washington, DC on December 13, 1995.

Harold W. Becker,

*Acting Program Director for Air Traffic Rules and Procedures.*

[FR Doc. 95-30777 Filed 12-18-95; 8:45 am]

BILLING CODE 4910-13-M

**14 CFR Part 39**

[Docket No. 95-NM-141-AD]

**Airworthiness Directives; Beech Model BAe 125-1000A and Hawker 1000 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to all Beech Model BAe 125-1000A and Hawker 1000 series airplanes. This proposal would require a detailed visual inspection to detect chafing damage to the hydraulic pipes adjacent to the

hydraulic module, and various follow-on actions. This proposal is prompted by reports of chafing damage between hydraulic pipes at three locations in the rear equipment bay adjacent to the hydraulic module. The actions specified by the proposed AD are intended to prevent such chafing damage to the hydraulic pipe and subsequent hydraulic fluid leakage; this condition may lead to failure of essential airplane systems.

**DATES:** Comments must be received by January 25, 1996.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-141-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Beech Aircraft Corporation, Manager Service Engineering, Hawker Customer Support Department, P.O. Box 85, Wichita, Kansas 67201-0085. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Tim Backman, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington 98055-4056; telephone (206) 227-2797; fax (206) 227-1149.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

Interested persons are invited to participate in the making of the proposed rule by submitting such written data, views, or arguments as they may desire. Communications shall identify the Rules Docket number and be submitted in triplicate to the address specified above. All communications received on or before the closing date for comments, specified above, will be considered before taking action on the proposed rule. The proposals contained in this notice may be changed in light of the comments received.

Comments are specifically invited on the overall regulatory, economic, environmental, and energy aspects of the proposed rule. All comments submitted will be available, both before and after the closing date for comments, in the Rules Docket for examination by interested persons. A report summarizing each FAA-public contact

concerned with the substance of this proposal will be filed in the Rules Docket.

Commenters wishing the FAA to acknowledge receipt of their comments submitted in response to this notice must submit a self-addressed, stamped postcard on which the following statement is made: "Comments to Docket Number 95-NM-141-AD." The postcard will be date stamped and returned to the commenter. Availability of NPRMs

Any person may obtain a copy of this NPRM by submitting a request to the FAA, Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-141-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056.

**Discussion**

The Civil Aviation Authority (CAA), which is the airworthiness authority for the United Kingdom, recently notified the FAA that an unsafe condition may exist on all Beech Model BAe 125-1000A and Hawker 1000 series airplanes. The CAA advises that it has received several reports of chafing damage between hydraulic pipes at three locations in the rear equipment bay adjacent to the hydraulic module. Investigation revealed the cause of such chafing damage has been attributed to the vibratory movement of the hydraulic pipes and their close proximity to other pipe runs, adjacent equipment, and structure in the rear equipment bay. These conditions, if not corrected, could result in chafing damage to the hydraulic pipe and subsequent hydraulic fluid leakage; this condition may lead to failure of essential airplane systems.

The manufacturer has issued Hawker Service Bulletin SB.29-95, dated March 24, 1995, which describes procedures for:

1. Performing a detailed visual inspection to detect chafing damage to the hydraulic pipes located aft of frame 21 and adjacent to the hydraulic module;
2. Performing a visual inspection to determine if adequate clearance exists between the pipes, and with other equipment or structure, if no chafing damage is detected;
3. Adjusting the pipe connections and/or clipping, if the clearance is inadequate;
4. Replacing the pipes with new pipes, if any chafing is detected beyond certain limits; and
5. Performing a pressure test, if any chafing damage is detected within certain limits, and replacement of the pipe with a new pipe, if necessary.

The CAA classified this service bulletin as mandatory in order to assure the continued airworthiness of these airplanes in the United Kingdom.

This airplane model is manufactured in the United Kingdom and is type certificated for operation in the United States under the provisions of section 21.29 of the Federal Aviation Regulations (14 CFR 21.29) and the applicable bilateral airworthiness agreement. Pursuant to this bilateral airworthiness agreement, the CAA has kept the FAA informed of the situation described above. The FAA has examined the findings of the CAA, reviewed all available information, and determined that AD action is necessary for products of this type design that are certificated for operation in the United States.

Since an unsafe condition has been identified that is likely to exist or develop on other airplanes of the same type design, the proposed AD would require a detailed visual inspection to detect chafing damage to the hydraulic pipes located aft of frame 21 and adjacent to the hydraulic module, and various follow-on actions (i.e., visual inspection, adjustment, replacement, pressure test). The actions would be required to be accomplished in accordance with the service bulletin described previously. If any chafing damage to other equipment or structure is found, repair would be required to be accomplished in accordance with a method approved by the FAA.

The FAA estimates that 27 airplanes of U.S. registry would be affected by this proposed AD, that it would take approximately 1 work hour per airplane to accomplish the proposed actions, and that the average labor rate is \$60 per work hour. Based on these figures, the cost impact of the proposed AD on U.S. operators is estimated to be \$1,620, or \$60 per airplane.

The cost impact figure discussed above is based on assumptions that no operator has yet accomplished any of the proposed requirements of this AD action, and that no operator would accomplish those actions in the future if this AD were not adopted.

The regulations proposed herein would not have substantial direct effects on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government. Therefore, in accordance with Executive Order 12612, it is determined that this proposal would not have sufficient federalism implications to warrant the preparation of a Federalism Assessment.

For the reasons discussed above, I certify that this proposed regulation (1) is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under the DOT Regulatory Policies and Procedures (44 FR 11034, February 26, 1979); and (3) if promulgated, will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act. A copy of the draft regulatory evaluation prepared for this action is contained in the Rules Docket. A copy of it may be obtained by contacting the Rules Docket at the location provided under the caption **ADDRESSES**.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Safety.

#### The Proposed Amendment

Accordingly, pursuant to the authority delegated to me by the Administrator, the Federal Aviation Administration proposes to amend part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

### **PART 39—AIRWORTHINESS DIRECTIVES**

1. The authority citation for part 39 continues to read as follows:

Authority: 49 USC 106(g), 40101, 40113, 44701.

#### **§ 39.13 [Amended]**

2. Section 39.13 is amended by adding the following new airworthiness directive:

Beech Aircraft Corporation (Formerly DeHavilland; Hawker Siddeley; British Aerospace, plc; Raytheon Corporate Jets, Inc.): Docket 95-NM-141-AD.

*Applicability:* All Model BAe 125-1000A and Hawker 1000 series airplanes, certificated in any category.

Note 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (b) of this AD to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition; or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any airplane from the applicability of this AD.

*Compliance:* Required as indicated, unless accomplished previously.

To prevent chafing damage to the hydraulic pipe and subsequent hydraulic fluid leakage; this condition may lead to failure of essential airplane systems; accomplish the following:

(a) Within 3 months after the effective date of this AD, perform a detailed visual inspection to detect chafing damage to the hydraulic pipes located aft of frame 21 and adjacent to the hydraulic module, in accordance with Hawker Service Bulletin SB.29-95, dated March 24, 1995.

(1) If no chafing damage is detected, prior to further flight, perform a visual inspection to determine if adequate clearance exists between the intersecting pipe runs, and between pipes and adjacent equipment or structure, in accordance with the service bulletin.

(i) If the clearance is adequate, no further action is required by this AD.

(ii) If the clearance is inadequate, prior to further flight, adjust the pipe connections and/or clipping in accordance with the service bulletin.

(iii) If any chafing damage to other equipment or structure is found, prior to further flight, repair it in accordance with a method approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate.

(2) If any chafing damage is detected and it is beyond the limits specified in paragraph 2.B.(4) of the service bulletin, prior to further flight, replace the damaged pipe with a new pipe in accordance with the service bulletin.

(3) If any chafing damage is detected within the limits specified in paragraph 2.B.(4) of the service bulletin, prior to further flight, perform a pressure test or replace the damaged pipe with a new pipe in accordance with the service bulletin.

(i) If the pipes are satisfactory, no further action is required by this AD.

(ii) If any pipe leaks and/or if any distortion occurs in or around the area of chafing damage, prior to further flight, replace the pipe with a new pipe in accordance with the service bulletin.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate. Operators shall submit their requests through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Standardization Branch, ANM-113.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Standardization Branch, ANM-113.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

Issued in Renton, Washington, on December 13, 1995.

Darrell M. Pederson,

*Acting Manager, Transport Airplane Directorate, Aircraft Certification Service.*

[FR Doc. 95-30748 Filed 12-18-95; 8:45 am]

BILLING CODE 4910-13-U

### **14 CFR Part 39**

[Docket No. 95-NM-172-AD]

### **Airworthiness Directives; Fokker Model F28 Mark 0100 Series Airplanes**

**AGENCY:** Federal Aviation Administration, DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** This document proposes the adoption of a new airworthiness directive (AD) that is applicable to certain Fokker Model F28 Mark 0100 series airplanes. This proposal would require a one-time measurement during refueling to determine the pressure in each collector tank; for certain airplanes, non-destructive test (NDT) inspections to detect cracking or deformations of the collector tank ribs on each wing, and repair, if necessary; and modification of top-hat stringers in each outer wing tank. This proposal is prompted by a report of damage to the ribs of the wing collector tank caused by over-pressure in the collector tank during refueling. The actions specified by the proposed AD are intended to prevent cracking and deformation of the wing collector tanks due to over-pressure, which could result in reduced structural integrity of the wing.

**DATES:** Comments must be received by January 30, 1996.

**ADDRESSES:** Submit comments in triplicate to the Federal Aviation Administration (FAA), Transport Airplane Directorate, ANM-103, Attention: Rules Docket No. 95-NM-172-AD, 1601 Lind Avenue, SW., Renton, Washington 98055-4056. Comments may be inspected at this location between 9:00 a.m. and 3:00 p.m., Monday through Friday, except Federal holidays.

The service information referenced in the proposed rule may be obtained from Fokker Aircraft USA, Inc., 1199 North Fairfax Street, Alexandria, Virginia 22314. This information may be examined at the FAA, Transport Airplane Directorate, 1601 Lind Avenue, SW., Renton, Washington.

**FOR FURTHER INFORMATION CONTACT:** Ruth E. Harder, Aerospace Engineer, Standardization Branch, ANM-113, FAA, Transport Airplane Directorate,